

TRADE: MECHANIC DIESEL
 ITI, MOHRAM HOMES, SA

STRAGACHU, MOHRAM.

2

SL NO	MO NO & NAME	DATE OF B. DOWN	TYPE OF MAINTENANCE	TRIP	B. DOWN MAINTENANCE	REMARKS	SIGNATURE		
							INST.	SVT.	FINAN. PRIN.
1.	MO-5 (17/6905370) Korleskar AV-1	28/03/15	Engine not starting B. Down	Fuel Fuel Inject clean	Line cleaning done Filter replaced. Injection assembly dismantled & refitted	engine started			
2.	MO-4 (17/69053457) Korleskar AV-1	08/04/15	Engine oil leakage from oil tube - G. Down.	oil new	tube replaced by me.	leakage stopped			
3.	MO-5 (17/69053470) Korleskar AV-1	21/05/14	Engine oil changed	2. lit	20W/40 Engine oil changed tube clamp,	old oil 50W/40 - fuel injector 200 - 20W/40.			
4.	MO-4 (17/69053453) Korleskar AV-1	14/02/12	Air trapped in fuel system.	Fuel	System bleeding done.				